

ASSEMBLY INSTRUCTION

CP1712-H-1656



A x4
Spec:



B x8
Spec: $\varnothing 11,8 \times \varnothing 10 \times L11$



C x8
Spec: 5/16*45



D x8
Spec: $\varnothing 8 \times \varnothing 14$



E x1
Spec: 5#



F x4
Spec:




FIG.
1




FIG.
2




FIG.
3




FIG.
4




FIG.
5












FIG.
6



DRAWER ASSEMBLY

CP1712-H-1656



DRAWER RENIVAL

ADJUSTABLE METHOD

